



ICBO Evaluation Service, Inc.

Accredited by the
American National Standards Institute

A subsidiary corporation of the International Conference of Building Officials

5360 WORKMAN MILL ROAD • WHITTIER, CALIFORNIA 90601-2298 • (562) 699-0543 • FAX (562) 695-4694

BOARD OF DIRECTORS

CHAIRMAN
JON S. TRAW, P.E.
PRESIDENT
INTERNATIONAL CONFERENCE
OF BUILDING OFFICIALS
WHITTIER, CALIFORNIA

MICHAEL CLACK, C.B.O.
ASSISTANT DIRECTOR/
BUILDING INSPECTOR
SAN ANTONIO, TEXAS

MICHAEL A. CLIBURN, C.B.O.
BUILDING SERVICES
ADMINISTRATOR
OREGON CITY, OREGON

JAMES M. HARPER, P.E.
CHIEF BUILDING OFFICIAL
HASTINGS, NEBRASKA

JACK A. NELSON, C.B.O.
MANAGER OF BUILDING SAFETY
LANSING, MICHIGAN

JOHN W. PARK, C.B.O.
ASSISTANT CITY MANAGER
OREM, UTAH

THOMAS M. SHIH, P.E.
BUILDING OFFICIAL
SANTA CLARA, CALIFORNIA

OFFICERS

PRESIDENT
JOHN NOSSE, P.E.

VICE-PRESIDENT
ROY FEWELL, C.B.O.

VICE-PRESIDENT
C.P. RAMANI, P.E., C.B.O.

VICE-PRESIDENT
KURT STOCHLIA, P.E.

SECRETARY
BOB D. HEINRICH, P.E.

January 18, 2001

Tim Welch
Vice President, Marketing
Won-Door Corporation
1865 South 3480 West
Salt Lake City, Utah 84104

ER-3890

Please reference this number
on all correspondence

Dear Mr. Welch:

This is in response to your letter dated January 16, 2001, regarding recognition of single- and bi-parting doors in ER-3890 (reissued October 1, 2000). There are many specifics related to construction, application, and installation of the doors that are not addressed by the evaluation report and which must be addressed by the fire door listing, as noted in Section 4.1 of the evaluation report. Evidence has been submitted to show that bi-parting Won-Door special-purpose fire doors have been tested and are listed by Underwriters Laboratories Inc. as being in compliance with UL 10B (UBC Standard 7-2, Part I), for protection of openings under Section 713 of the 1997 *Uniform Building Code*. As a result, it is our opinion that bi-parting Won-Door special-purpose fire doors are recognized within the evaluation report, provided the door assembly in question is also within the scope of the UL listing.

I hope this information is satisfactory for your needs. If you have any questions, please contact me at (562) 699-0543, extension 3289.

Yours very truly,

Michael Beaton, P.E.
Senior Staff Engineer

MB/lh

Conference Resource Centers: 6130 Stoneridge Mall Road, Suite 120 • Pleasanton, California 94588 • (925) 734-3080
335 Ridgepoint Drive • Carmel, Indiana 46032 • (317) 706-1677
2900 N.E. 60th Street, Suite 206 • Gladstone, Missouri 64119 • (816) 455-3330
3355 Bee Caves Road, Building 4, Suite 404C • Austin, Texas 78746 • (512) 306-8258
2122-112th Avenue, N.E., Suite B-300 • Bellevue, Washington 98004 • (425) 451-9541
377 Ponce de Leon Avenue • P.O. Box 192017 • Hato Rey, Puerto Rico 00919 • (787) 753-5575
Chile 990, Piso 2, Dept. "G" • 5500 Ciudad, Mendoza, Argentina • (54)-261-425-5310